




Sets in 15 to 30 seconds  
with no clamping required



Suitable for porous  
& non-porous substrates



Self-piercing tube  
for precise &  
controlled dosing



Triple resistance: resistant to  
moisture, shock & freezing  
temperatures